



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

Incident List

Basic

Property Information

Incident # 22-00143830

Property Use: Multifamily dwelling

Incident Type: Building fire

Mixed Property Use:

Aid Given or Received: None

Hazmat Release: None

Alarm Date/Time: 11/16/2022 08:40:12

Detector Alert:

First Arrival Date/Time: 11/16/2022 08:43:00

Property Loss: \$5000000

Last Clear Date/Time: 11/17/2022 06:12:21

Property Value: \$0

Action Taken: Refer to proper authority
 HazMat detection, monitoring, sampling, & analysis
 Investigate
 Incident command
 Provide first aid & check for injuries
 Provide basic life support (BLS)
 Provide advanced life support (ALS)
 Transport person
 Evacuate area
 Establish safe area
 Notify other agencies.
 Provide information to public or media

Content Loss: \$600000

Officer In Charge: BC5779 / Bailey, Charles

Content Value: \$0

Summary

Exposure: 0

Personnel Suppression: 62

Station: 08

EMS: 28

Shift: C

Other: 58

Alarms: 0

Apparatus Suppression: 19

Battalion: B3

EMS: 16

Other: 40

Narrative



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

OC700 arrived well into the incident. Upon my arrival all patients has been transported and the overwhelming majority of the fire had been extinguished. Detailed operational summaries can be found in the respective unit reports.

OC700 assumed command in order to coordinate the "whole of County" response. Established five objectives:

- 1-Ensure awareness of situation: Use observers | Assign scribes | Use MSTeams | Maintain contact list (ICS205T)
- 2-Limit damages: Limit spread | Avoid additional damage to structures | Avoid additional damage to personal belongings
- 3-Reduce 2nd order impact to community: Reconsider road closures | Consider impact to local business | Reduce incident footprint
- 4-Secure the scene: Control entry | Only restrict what is necessary
- 5-Support community recovery: Ensure OEMHS is properly resourced | Provide logistical support to OEMHS

Command: OC700

SpecOps Branch: SpecOps AC | Investigations Group & Tech Rescue Group

Logistics Section: OEMHS-Laboy, FRS Baltrotsky

Suppression Branch: BC703

Security Branch: GPD Lt.

Community Welfare Branch OEMHS-Cristomos

WUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

Fire	
Property	Equipment Mobile Involved
# of Residential Units: 12	Equipment Involved: None
# of Bldgs Involved: 1	Equipment Brand:
# of Acres Burned: 0	Equipment Model:
On Site Material / Use:	Serial #:
	Equipment Year: 0
	Equipment Power:
	Equipment Portability:
	Mobile Involved: None
	Mobile Type:
	Mobile Make:
	Mobile Model:
	Mobile Year: 0
	Mobile Lic Plate:
	State:
	VIN:

WUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

Structure Fire		Detector	
Structure		AES Category	
Structure Type:	Enclosed building	Detector Presence:	Undetermined
Building Status:	Occupied and operating	Detector Type:	
Stories Above Grade:	3	Power Supply:	
Stories Below Grade:	0	Operation:	
Sory of Fire Origin:	2	Effectiveness:	
Fire Origin Below Grade?	No	Failure Reason:	
Fire Spread:	Confined to building of origin	AES Presence:	None Present
Total Square Feet:	2400	AES Type:	
Length In Feet:	60	AES Operation:	
Width In Feet:	40	# of Sprinkler Heads:	0
Minor Damage (1%-24%):	0	AES Failure Reason:	
Significant Damage (25%-49%):	0		
Heavy Damage (50%-74%):	0		
Extreme Damage (75% - 100%):	0		
Type of Item Flame Spread :			
Type of Material:			

WUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

<u>Unit</u>	<u>Dispatch Date Time</u>	<u>Enroute Date Time</u>	<u>Arrival Date Time</u>	<u>Hosp Trans Date Time</u>	<u>Hosp Arr Date Time</u>	<u>Cancelled Date Time</u>	<u>Clear Date Time</u>
A723	11/16/2022 08:52:22	11/16/2022 08:52:34	11/16/2022 09:19:26				11/16/2022 09:46:49
Inventory Usage:	NO EQUIPMENT USED			Unit Action Taken: Action taken, Other			
Unit Personnel:	Burkhart, Riley		Officer in Charge (Or one person unit)				
	Dolan, Kevin		DRIVER				
Unit Narrative:	Staged in EMS staging area. Placed in service by EMS Branch Supervisor.						
CT714	11/16/2022 09:51:33	11/16/2022 09:51:33	11/16/2022 09:51:33				11/16/2022 09:58:08
Inventory Usage:				Unit Action Taken:			
Unit Personnel:	Graham, Bradley		Officer in Charge (Or one person unit)				
Unit Narrative:							
C708	11/16/2022 09:16:55	11/16/2022 09:16:55	11/16/2022 09:36:21				11/16/2022 09:38:34
Inventory Usage:	NO EQUIPMENT USED			Unit Action Taken: Action taken, Other			
Unit Personnel:	Knopp, Kenneth		Officer in Charge (Or one person unit)				
Unit Narrative:	AOS as part of incident stabilization effort. Rerouted enroute to support an additional 31 Box alarm on Ellington Pl.						
PE720	11/16/2022 08:40:58	11/16/2022 08:42:10	11/16/2022 09:02:23				11/16/2022 10:26:18
Inventory Usage:	NO EQUIPMENT USED			Unit Action Taken: Provide manpower			
Unit Personnel:	Marteli, Simon		Left				
	Jackson, Lonnie		Officer in Charge (Or one person unit)				
	Lee, Trent		DRIVER PRIMARY				
	Long, Ramon		Right				
Unit Narrative:	PE720 DISPATCHED AS HAZMAT SUPPORT ON THE 8 BOX. PE720 PERSONNEL WAITED TO BE DEPLOYED DURING THE INCIDENT.						



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

RS703					
11/16/2022 08:40:58	11/16/2022 08:42:14	11/16/2022 08:52:27			11/16/2022 10:42:31
Inventory Usage: SCBA TOOL, HAND, LRG (SHOVEL, AXE, etc) TOOL, HAND, SM (HAMMER, WRENCH, etc)		Unit Action Taken: Fires, rescues & hazardous conditions, Other Forcible entry			
Unit Personnel: Eiskant, Daniel Kelleher, Jesse Dodson, Steven		Officer in Charge (Or one person unit) DRIVER CERTIFIED Right			
Unit Narrative: DISP FOR BLDG FIRE W/EXPLOSION. FORCED ENTRY AND PERFORMED PRIMARY SEARCHES, NEGATIVE. PERFORMED 2ND SEARCHES AS REQ BY COMMAND.					
PE733					
11/16/2022 08:47:27	11/16/2022 08:49:30	11/16/2022 09:09:53			11/16/2022 10:42:52
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Fire control or extinguishment, other			
Unit Personnel: JENKINS, JOSEPH Knowles, Philip Schilling, Stephen Shadle, William		Right DRIVER Officer in Charge (Or one person unit) Left			
Unit Narrative: DISPATCHED 2ND ALARM, BUILDING FIRE, ARRIVED IN STAGING, COMMAND GAVE ASSIGNMENT TO STRETCH A LINE TO 824 QUINCE ORCHARD BLVD, PULLED A CROSSLAY AND BUNDLE FROM PE708, INVESTIGATED ATTIC AREA FOR EXTENSION, WE OPENED UP THE CEILING AREA ADJACENT TO THE FIRE BUILDING AND CHECKED THE ENTIRE ATTIC AREA WITH AT735, NO EXTENSION, WE ALSO PERFORMED A PRIMARY AND SECONDARY SEARCH OF THE ENTIRE BUILDING (NEGATIVE), SENT TO REHAB PER COMMAND, PLACED IN SERVICE BY COMMAND, PE733 READY, CAPT SCHILLING					

WUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

BC705

11/16/2022 08:40:58	11/16/2022 08:41:10	11/16/2022 08:46:26			11/16/2022 10:50:01
Inventory Usage: SCBA FLASHLIGHT		Unit Action Taken: Search Incident command			
Unit Personnel: Fitch, Monte		Officer in Charge (Or one person unit)			
Unit Narrative: aos and reported to command, assigned to manage resources working, evaluate conditions and needs and report back to command. Reported from the charlie side that there were no visible victims, assessed conditions. reported to the alpha side and made entry into the delta exposure. found the lowest level apartment in the A/B quadrants opened and no smoke, did not make entry initially because wanted to evaluate collapse load above first. Had crews access the apartments in the c/d quadrants on all floors and perform searches. I assessed second floor apartment and found lean-to collapse and unable to enter apartment due to collapsed materials. Conducted a hail search with no response. went to the top floor and found the roof gone and a collapse, did not make entry but could see most of apartment. Entered apartment on top floor in c/d quadrant and found crews knocking fire at the fire wall with a large portion of the roof burned away. Had all crews exit building and move to the delta 1 exposure and check for extension and victims. reported all findings to command and advised when out of the building. Worked with crews to complete searches in delta 1 exposure and notify command. Circle check of buildings and operations, confirmed resources out of collapse zone, had a master stream set up on charlie side.					

WUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

EMB700B

11/16/2022 08:43:13 11/16/2022 08:43:13 11/16/2022 09:11:49 11/16/2022 10:47:26

Inventory Usage: OTHER EQUIPMENT (Add desc in Notes) Unit Action Taken: Incident command

Unit Personnel: Burns, Timothy Officer in Charge (Or one person unit)

Unit Narrative: Responded for building fire with explosion.

Arrived on scene and offered to command that I take EMS Branch to which he agreed.

Established EMS Branch on 7A5, designated casualty collection point in warm zone between E729 and AT703.

Designated EMS703 as triage group supervisor functioning in the CCP. Expanded that CCP to a treatment area with EMS702 and A708B.

Had remaining transport units not committed to the scene stage at QO Blvd and Firstfield.

Eventually transitioned treatment area to pool house adjacent to fire building under supervision of EMS702 and ALS708.

EMS703 transitioned to transportation/disposition supervisor.

A708B/ALS708 became fireground rehab.

Worked through treatment and transport of 10 patients with two additional refusals on scene prior to disbanding the EMS branch.

Once all patients had been transported, treatment area (pool house) became an area of refuge for affected residents. Maintained a presence there with A732.

Nothing further.


CT705

11/16/2022 09:00:29 11/16/2022 09:02:53 11/16/2022 10:57:44 11/16/2022 10:57:44

Inventory Usage: NO EQUIPMENT USED Unit Action Taken: Cancelled en route

Unit Personnel: Rudolph, Natalie DRIVER

Unit Narrative: Placed In Service While Responding






FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

M708						
11/16/2022 08:40:58	11/16/2022 08:41:16	11/16/2022 08:44:27	11/16/2022 09:46:16	11/16/2022 10:04:18		11/16/2022 10:33:38
Inventory Usage: EMS, STRETCHER, SPECIFY EMS, VITALS MONITOR FORCIBLE ENTRY TOOL, HAND LADDER, OVER 30 FEET SCBA			Unit Action Taken: Provide basic life support (BLS) Evacuate area			
Unit Personnel: Turcotte, Jeremy		Officer in Charge (Or one person unit)				
Leizear, Matthew		DRIVER				
Unit Narrative: DISP FOR BUILDING FIRE WITH EXPLOSION AND ENTRAPMENT. AS PE708 AND PAT708 PARKED ON SIDE ALPHA, M708 POSITIONED WITH A708 ON SIDE C. AS WE WERE EXITING M708, A FRANTIC CITIZEN CAME RUNNING UP TO M708 M2 AND STATED "Y [REDACTED] THERE IS A MOM WITH [REDACTED] BABY ON THE THIRD FLOOR BACK HERE AND THEYRE ABOUT TO JUMP." M708 CREW QUICKLY DROPPED PPE AND SCBA, AND MOVED TO SIDE C OF THE STRUCTURE. SIDE C HAD HEAVY FIRE CONDITIONS WITH PARTIAL COLLAPSE OF 826, AND HEAVY SMOKE COMING FROM 828, WHICH WAS THE REPORTED BUILDING AND APARTMENT THE VICTIMS WERE IN. A708 WAS BRINGING AROUND A 35' EXTENSION LADDER, WHICH WAS PLACED AND M2 AND T3 FROM PAT708 ENTERED THE STRUCTURE TO PERFORM VEIS. THE SEARCH PROVED NEGATIVE, AND WE EXITED THE BUILDING. M708 WAS THEN PART OF THE EMS SECTOR, AND WAS EVENTUALLY TASKED WITH TRANSPORTING A TRAUMA PT TO SUBURBAN HOSPITAL FOR JUMPING OUT OF THE 3RD STORY WINDOW. PT HAD MINOR INJURIES. AFTER TRANSFER OF CARE OF SUBURBAN HOSPITAL, WE CLEARED THE CALL.						
M703						
11/16/2022 08:52:22	11/16/2022 08:52:52	11/16/2022 09:03:01	11/16/2022 09:59:21	11/16/2022 10:11:51		11/16/2022 10:35:04
Inventory Usage: EMS, JUMP BAG EMS, PULSE OXIMETER EMS, STRETCHER, SPECIFY			Unit Action Taken: Provide basic life support (BLS)			
Unit Personnel: Swann, Morgan		Officer in Charge (Or one person unit)				
Schuler, Peter		Officer in Charge (Or one person unit)				
Unit Narrative: AOS to find an adult [REDACTED] patient that was in need of a check-up. The patient was transported priority three to HCH Germantown.						






FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

AT735						
11/16/2022 08:47:27	11/16/2022 08:49:11	11/16/2022 09:03:01				11/16/2022 10:36:12
Inventory Usage:		SCBA TOOL, HAND, LRG (SHOVEL, AXE, etc) THERMAL IMAGER		Unit Action Taken: Salvage & overhaul		
Unit Personnel:		Zulick, Adam Right Wiseman, Michael DRIVER PRIMARY Damico, Anthony Officer in Charge (Or one person unit)				
Unit Narrative: Assigned to check building 824 for extension with PE733. Hooked the ceilings and walls that adjoined 826 on the third floor. No extension found. Returned to staging and we were not assigned any other tasks by command.						
A708						
11/16/2022 08:40:58	11/16/2022 08:41:13	11/16/2022 08:44:29	11/16/2022 09:45:30	11/16/2022 09:56:35		11/16/2022 10:38:41
Inventory Usage:		EMS, JUMP BAG EMS, PULSE OXIMETER EMS, STRETCHER, SPECIFY		Unit Action Taken: Provide basic life support (BLS) Transport person		
Unit Personnel:		Silberhorn, Jonathan DRIVER Becka, Drake Officer in Charge (Or one person unit)				
Unit Narrative: Transported 2 patients, [REDACTED] and [REDACTED] after house fire. Both patients were BLS P3 and transported to SGAH.						
PE723						
11/16/2022 08:47:27	11/16/2022 08:48:39	11/16/2022 09:00:35				11/16/2022 10:38:39
Inventory Usage:		THERMAL IMAGER FLASHLIGHT		Unit Action Taken: Fire control or extinguishment, other Salvage & overhaul		
Unit Personnel:		Bevard, Thomas Officer in Charge (Or one person unit) Kime, Tyler Left Eisenacher, Ryan Right Lyon, Matthew DRIVER CERTIFIED				
Unit Narrative: Dispatched on second alarm. Arrived to scene and staged. Given assignment to go to building 830 apt 202 and relieve PE722. Performed salvage and overhaul, ensured hot spots were extinguished. Crew went through rehab.						





FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878


RS717					
11/16/2022 08:42:23	11/16/2022 08:42:33	11/16/2022 08:59:27			11/16/2022 10:40:36
Inventory Usage:	FORCIBLE ENTRY TOOL, HYDRAULIC HYD RESCUE TOOL, POWER LADDER, 20-30 FEET STOKES BASKET TOOL, HAND, LRG (SHOVEL, AXE, etc) TOOL, HAND, SM (HAMMER, WRENCH, etc)		Unit Action Taken:	Provide manpower Provide equipment	
Unit Personnel:	Gotwols, Christopher Right Gray, Kerrington DRIVER CERTIFIED Ward, Scott Officer in Charge (Or one person unit)				
Unit Narrative:	RS717 DISPATCHED ON THE RID FOR THE BUILDING EXPLOSION. ARRIVED AND WORKED WITH AT703 TO ASSUME RIG FUNCTIONS. CREATED SECOND SET OF RIG CASHE ON THE C SIDE OF THE BUILDING. PERSONEL STAGED ON C SIDE TO KEEP EYES ON CREWS WORKING IN THE REAR. UNIT CLEARED BY COMMAND.				
B717					
11/16/2022 10:37:58	11/16/2022 10:37:58			11/16/2022 10:40:31	11/16/2022 10:40:31
Inventory Usage:	NO EQUIPMENT USED		Unit Action Taken:	Cancelled en route	
Unit Personnel:	Gregory, Richard Officer in Charge (Or one person unit)				
Unit Narrative:	Placed In Service While Responding				
HM707					
11/16/2022 08:40:58	11/16/2022 08:43:50	11/16/2022 09:56:46			11/16/2022 10:15:43
Inventory Usage:	HAZ MAT EQUIP, SPECIFY		Unit Action Taken:	Action taken, Other HazMat detection, monitoring, sampling, & analysis	
Unit Personnel:	Hall, Jaron Right Wu, Yu Lun Left Joslyn, George DRIVER Sanchez, Raymond Officer in Charge (Or one person unit)				
Unit Narrative:	ASSISTED WITH METERING AND WAS DIRECTED TO SHUT GAS OFF AT THE STREET. ATTEMPTED TO LOCATE GAS SHUTOFF. ACCESS WAS VERY CHALLENGING DUE TO DEPTH AND WATER AND MUD. GAS COMPANY ARRIVED AND HM707 COORDINATED WITH GAS COMPANY AND COMMAND. PLACED IN SERVICE.				



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

PE735					
11/16/2022 08:47:27	11/16/2022 08:47:53	11/16/2022 09:02:59			11/16/2022 10:22:28
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Standby			
Unit Personnel: McShane, Lee		Officer in Charge (Or one person unit)			
Shaffer, William		DRIVER			
Kumm, Henry		Right			
Reid, Dwight		Left			
Unit Narrative: AOS - assigned as Staging Officer by Command for duration					
EMS702					
11/16/2022 08:46:37	11/16/2022 08:46:37	11/16/2022 08:57:00			11/16/2022 10:23:27
Inventory Usage: OTHER EQUIP, BLS, SPECIFY		Unit Action Taken: Provide first aid & check for injuries			
Unit Personnel: McDonald, Michael		Officer in Charge (Or one person unit)			
Unit Narrative: enroute notified EMRC of MCI due to the nature of the dispatch					
consulted with all area hospitals to ascertain how many beds each could potentially be used for patients					
arrived on scene on the incident and met up with the EMS Branch					
performed a 360 of the building to check if there were any wounded patients in the area, and directed them to the casualty collection point (CCP)					
once the CCP was established worked with EMS703 to re triage all patients in the CCP and develop a plan for transporting					
assisted with transport of patients to area hospitals					
after last patient was transported met back up with EMS branch, and was placed in service					
ALS708					
11/16/2022 08:40:58	11/16/2022 08:41:57	11/16/2022 08:45:13			11/16/2022 10:24:00
Inventory Usage: EMS, JUMP BAG		Unit Action Taken: Emergency medical services, Other			
EMS, PULSE OXIMETER					
EMS, VITALS MONITOR					
Unit Personnel: Rivas, Alexander		Officer in Charge (Or one person unit)			
Unit Narrative: DISPATCHED FOR A FIRE. AOS AND ASSISTED WITH PATIENTS.					





FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

EMS703					
11/16/2022 08:44:48	11/16/2022 08:44:54	11/16/2022 08:53:23			11/16/2022 11:27:16
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Action taken, Other			
Unit Personnel: Dugan, Peter		Officer in Charge (Or one person unit)			
Unit Narrative: RESPONDED FOR THE BUILDING FIRE WITH BUILDING EXPLOSION. AOS AND POSITIONED NEXT TO THE ELEMENTARY SCHOOL. UPON ARRIVAL AT THE SCENE, EMIHS BC700B INITIATED THE MCI BY ASSUMING THE EMS BRANCH. DIRECTLY REPORTED TO EMS BRANCH ON 7A5 AND WAS INITIALLY THE TRIAGE OFFICER BUT EVENTUALLY MIGRATED TO BECOME THE TRANSPORT/DISPOSITION/COMMUNICATIONS OFFICER. A TOTAL OF 10 PATIENTS WERE TRANSPORTED TO AREA HOSPITALS. COORDINATED ALL TRANSPORTS.					
B708					
11/16/2022 10:29:28	11/16/2022 10:29:28			11/16/2022 11:36:34	11/16/2022 11:36:34
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Cancelled en route			
Unit Personnel: Carlson, Christopher		Officer in Charge (Or one person unit)			
Unit Narrative: Placed In Service While Responding					
E725					
11/16/2022 08:43:46	11/16/2022 08:43:54	11/16/2022 08:59:47			11/16/2022 11:55:58
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Provide manpower			
Unit Personnel: Dahlen, Sean		DRIVER			
Benedict, Scott		Officer in Charge (Or one person unit)			
Dominick, Keith		Left			
Hilley, Jospheh		Right			
Unit Narrative: Provided manpower for the hazmat compliment on the building fire with explosion					

WUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

PE722					
11/16/2022 08:47:27	11/16/2022 08:47:35	11/16/2022 08:51:56			11/16/2022 11:16:46
Inventory Usage: HANDLINE, 1 1/2 - Put # ft in Quantity TOOL, HAND, LRG (SHOVEL, AXE, etc) THERMAL IMAGER		Unit Action Taken: Extinguishment by fire service personnel			
Unit Personnel: Fritz, Jeffrey Juarez, Julio Hicks, Brenda Johnson, William		Officer in Charge (Or one person unit) DRIVER CERTIFIED Right Left			
Unit Narrative: Dispatched first due engine on the second alarm. Assigned by command to building 830 to check for extension. Proceeded to the second floor and forced the door to apartment 201. Opened ceilings adjacent to the firewall and flowed a handline in the attic space thru the hole in the block fire wall. relieved by E723 and reported to rehab. Released by command					
A722					
11/16/2022 08:52:22	11/16/2022 08:53:44	11/16/2022 09:04:11			11/16/2022 12:08:20
Inventory Usage: EMS, JUMP BAG EMS, PULSE OXIMETER		Unit Action Taken: Provide first aid & check for injuries Provide basic life support (BLS) Transport person			
Unit Personnel: Washington, Shakevin Holloway, Johnathan		Officer in Charge (Or one person unit) DRIVER			
Unit Narrative: Treated and transported patient to hospital on MAB726					

WUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

SA700				
11/16/2022 08:45:21	11/16/2022 08:45:21	11/16/2022 08:50:29		11/16/2022 12:20:19
Inventory Usage:	SCBA THERMAL IMAGER FLASHLIGHT Pak Tracker MX6-Meter	Unit Action Taken:	ISSO/ISO	
Unit Personnel:	Neal, Paul	Officer in Charge (Or one person unit)		
Unit Narrative:	<p>AOS parked on QO Blvd next to school entrance, dressed and reported to ICP. Approached ICP, waived at IC who acknowledged me "doing a 360". Surveyed side A as crews continued firefighting. Building 826 & 828 had structure compromise. Walked over to side B then walked around to side C via side D. Arrived on side C immediately backed crews out of the collapse zone. Face to face Capt Rice who was side Charlie about hazards of the collapse zone. He was ok. Discussed the uncontrolled gas fed fire. Waiting for Wash Gas to shut gas off. Walked backed around to side A and began moving crews back out of the collapse zone. IC order crews out of 828 not to enter this is a defensive OPS. Moved crews back. Placed Hazard Line Tape on side A defining the collapse/ no entry zone. Walked back to side C via side B. Placed Hazard Line Tape on side C and advised crews collapse /no entry zone defined. Radio IC to advise Hazard Line tape in place collapse/ no entry zone setup. Master streams flowing, I pulled crews further back away from structure. Monitored scene walking back and forth from A to C side. Called to ICP for a meeting with C700 & DOC with BC705 ref making entry into building 828 C/D quads only. We have an uncontrolled gas fed fire in building 826. I asked about electric and water being controlled. BC705 wanted to enter 828 to do a secondary search of the C/D quads all three floors. I concur with making entry with a RIT standing by and Master streams stopped. All parties in agreement, plan carried out. AT703 crew handled RIT on side A. I watched then went to side C. Minor hot spots in 3rd floor area. Mission completed and crews out of 828. Did a face to face with BC705 on structural integrity of 828 C/D quads. Lots of water, minor hot spots. Quad A/B collapsed not accessible. Continued to monitor collapse zones and personnel operating around area. IC asked me to recon T725 and T734 to see if they can back out of the grass area. T725 needs towed out, T734 ok to back out. Radio IC of needs for T725 only. Returned to ICP for Senior staff meeting with IC, OPS700, C700 and other agencies. Meeting over met up with ATF and MCFRS Engineer as they walked around the site looking at the structural stability issues. Walked from side A to B to C then back to side A. Face to face with IC, went in service since we are transitioning to TRT mode. Packed up and went to rehab and then in service. Deconned at unit.</p>			
ALS708				
11/16/2022 13:19:16	11/16/2022 13:19:47	11/16/2022 13:25:11		11/16/2022 13:55:11
Inventory Usage:	EMS, JUMP BAG EMS, OXYGEN EMS, PULSE OXIMETER EMS, VITALS MONITOR	Unit Action Taken:	Provide advanced life support (ALS)	
Unit Personnel:	Rivas, Alexander	Officer in Charge (Or one person unit)		
Unit Narrative:	DISPATCHED TO ASSIST TWO PATIENTS. BOTH REFUSED			



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

A708					
11/16/2022 13:29:40	11/16/2022 13:30:22			11/16/2022 13:34:58	11/16/2022 13:34:58
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Cancelled en route			
Unit Personnel: Silberhorn, Jonathan		DRIVER			
Becka, Drake		Officer in Charge (Or one person unit)			
Unit Narrative: Placed In Service While Responding back to fire.					
EMS704					
11/16/2022 10:21:03	11/16/2022 10:21:03			11/16/2022 13:14:28	11/16/2022 13:14:28
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Cancelled en route			
Unit Personnel: Koehn, Timothy		Officer in Charge (Or one person unit)			
Unit Narrative: Placed In Service While Responding					
A728					
11/16/2022 08:42:50	11/16/2022 08:43:23	11/16/2022 08:55:35			11/16/2022 14:42:22
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Action taken, Other			
Unit Personnel: Alfaro, Jorge		Officer in Charge (Or one person unit)			
Forse, Brian		DRIVER			
Unit Narrative: ASSISTED HM728					

WUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

HM728				
11/16/2022 08:40:58	11/16/2022 08:44:09	11/16/2022 08:55:24		11/16/2022 14:33:37
Inventory Usage: METER, MULTI-GAS		Unit Action Taken: Identify, analyze hazardous materials HazMat detection, monitoring, sampling, & analysis Investigate		
Unit Personnel: Alfaro, Jorge		Right		
Bencosme, Anselmo		Officer in Charge (Or one person unit)		
Miles, Russell		DRIVER CERTIFIED		
Lehner, Daniel		Left		
Unit Narrative: We were dispatched as the hazmat resource for the reported building fire with an explosion. . Initial units arrived on the scene to find two three story garden style apartment buildings on fire after an explosion. We arrived on the scene and established a hazmat staging area at Brown Station Elementary School and were joined by PE720, HM707, and A728. Once the fire was under control, we were instructed by command to meter several adjacent apartment buildings for any possible natural gas. Several apartment buildings were metered which include the 700, 800, 900 blocks of Quince Orchard BLVD. Zero reading were received throughout. Command was advised and we returned into service.				
BC703				
11/16/2022 08:40:58	11/16/2022 08:41:51	11/16/2022 08:50:42		11/16/2022 14:16:53
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Incident command		
Unit Personnel: Mann, Stephen		Officer in Charge (Or one person unit)		
Unit Narrative: Dispatched for a reported building explosion w/ fire IAO 826 Quince Orchard Blvd. PSCC advised that they had multiple 911 calls w/ reports of same with several different addresses given. Units from Co. 8 AOS to find a 3 story apartment building with fire on all 3 floors and collapse. Upon Co. 8's arrival PSCC advised that a caller advised that a [REDACTED] with a child were on the 3rd floor balcony. Message was acknowledged by both PE708 and PAT708. BC703 AOS and established stationary CP on side "A". A second alarm, multi-patent dispatch and TRT response were requested. Command began to direct the evacuation of occupants and address the horizontal fire spread. EMSBC AOS and was assigned the EMS division and given 7A5 and all units from the multi-patent dispatch as well as EMS703 and the transport units on the box and RID. Due to the significant fire volume and building instability from the collapse, 826 was immediately deemed exterior only and focus was to ensure that all occupants from 824, 828, and 830 were removed and cared for. BC705 was assigned as the 828 division with E708, E731, tasked to search and evacuate all units and cut off horizontal extension. E722 was assigned as the 830 division tasked with evacuating all floors and ensuring no extension. PE733 and AT735 assigned to 824 with the same objectives. PE734 assigned the C division supervisor along with PE732, T734 and T725 tasked with knocking fire and cutting off horizontal extension. PE733 and AT735 assigned to 824 with the same objectives. PE729 assigned to knocking fire on side A.				



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

MAB726						
11/16/2022 09:05:31	11/16/2022 09:16:33	11/16/2022 09:49:34	11/16/2022 10:05:03			11/16/2022 15:36:44
Inventory Usage: EMS, JUMP BAG			Unit Action Taken: Transport person			
Unit Personnel: Gerondakis, Sean		DRIVER				
Unit Narrative: transport 5 to sub						
A732						
11/16/2022 09:55:02	11/16/2022 09:55:24	11/16/2022 10:07:01				11/16/2022 15:51:41
Inventory Usage: EMS, JUMP BAG			Unit Action Taken: Emergency medical services, Other Provide basic life support (BLS)			
Unit Personnel: Crocker, Michael		Officer in Charge (Or one person unit)				
Davidson, Molly		DRIVER				
Unit Narrative: assessed a few patients no transports						
HM728						
11/16/2022 14:39:19	11/16/2022 14:39:19	11/16/2022 14:39:19				11/16/2022 15:29:46
Inventory Usage: METER, MULTI-GAS			Unit Action Taken: Investigate			
Unit Personnel: Bencosme, Anselmo		Officer in Charge (Or one person unit)				
Miles, Russell		DRIVER CERTIFIED				
Lehner, Daniel		Left				
Fuentes, Johanna		Right				
Unit Narrative: We were dispatched for the reported odor of natural gas. We arrived on the scene and were instructed by command to investigate a reported odor of natural gas in a building several blocks away from earlier morning explosion. An investigation was conducted on the reported building and several adjacent buildings with a MX6 PID meter with zero readings received throughout. Command was advised and were placed in service.						





FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

T734

11/16/2022 08:40:58 11/16/2022 08:41:17 11/16/2022 08:47:00 11/16/2022 14:59:52

Inventory Usage:	FORCIBLE ENTRY TOOL, HAND FORCIBLE ENTRY TOOL, HYDRAULIC HYD RESCUE TOOL, MANUAL LADDER, AERIAL LADDER, UNDER 20 FEET LADDER, 20-30 FEET LADDER, 20-30 FEET SCBA TOOL, HAND, LRG (SHOVEL, AXE, etc) THERMAL IMAGER	Unit Action Taken:	Fire control or extinguishment, other Salvage & overhaul Confine fire (wildland) Search Forcible entry
-------------------------	---	---------------------------	--

Unit Personnel:	Thomas, Ralph TILLER Harding, John DRIVER PRIMARY Riddle, James Officer in Charge (Or one person unit)
------------------------	---

Unit Narrative: Dispatched 2nd due truck, positioned on C/D corner.

Reports of people on balcony of side C. Scanned balconies on side C, no one found. Truck driver placed multiple ladders on side C.


Made entry to 828 from C side. Directed to top floor apartment in 828 for search and overhaul. Directed to leave 828 and make stop in 830.

Multiple doors forced, in 826, 828, and 830.

Primary searches completed by T734:
 -826 terrace level, approximately 10x10 common space
 -828 terrace level apartment and top floor apartment
 -830 Second and Third floor apartments

Ceilings hooked:
 -828 top floor apartment
 -830 top floor apartment

Salvage done throughout structures.





FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

BE717

11/16/2022 10:45:06	11/16/2022 10:45:20	11/16/2022 11:10:49		11/16/2022 16:29:46
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Provide manpower		
Unit Personnel: Mills, Richard		Officer in Charge (Or one person unit)		
Unit Narrative: TRT non consolidated member response.				

CT717

11/16/2022 09:00:29	11/16/2022 09:04:59	11/16/2022 09:50:40		11/16/2022 16:30:40
Inventory Usage: OTHER EQUIPMENT (Add desc in Notes)		Unit Action Taken: Assistance, Other		
Unit Personnel: Eanes, Michael		Officer in Charge (Or one person unit)		
Unit Narrative: Canteen services				

UT727

11/16/2022 11:13:04	11/16/2022 11:16:03	11/16/2022 11:24:33		11/16/2022 16:34:25
Inventory Usage:		Unit Action Taken:		
Unit Personnel:				
Unit Narrative:				

CT708

11/16/2022 09:12:38	11/16/2022 09:13:00	11/16/2022 09:22:01		11/16/2022 16:54:44
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Assistance, Other		
Unit Personnel: Carlson, Christopher		DRIVER		
Dagalakis, Maria		OTHER		
Unit Narrative: ASSISTED UNITS ON SCENE				


WUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

PR5729						
11/16/2022 08:53:36	11/16/2022 08:54:02	11/16/2022 08:57:40				11/16/2022 16:45:25
Inventory Usage:		HYD RESCUE TOOL, MANUAL SCBA THERMAL IMAGER	Unit Action Taken: Assistance, Other			
Unit Personnel:		Cochran, Daniel	Officer in Charge (Or one person unit)			
		Anderson, Scott	Left			
		Jordan, Brian	DRIVER			
		Rutledge, Justin	Right			
Unit Narrative:		rescue squad on the trt response, no actions				
TR700B						
11/16/2022 08:53:36	11/16/2022 09:00:01	11/16/2022 09:30:04				11/16/2022 16:43:53
Inventory Usage:		TRT Equip, Specify	Unit Action Taken: Provide manpower Provide apparatus Provide equipment			
Unit Personnel:		Lauret, Craig	DRIVER			
		Rodriguez, Terrance	Officer in Charge (Or one person unit)			
Unit Narrative:		TR700B dispatched as TRT asset on building explosion. See TR700 report for details.				
M731						
11/16/2022 08:42:23	11/16/2022 08:42:52	11/16/2022 08:47:42	11/16/2022 08:59:12	11/16/2022 09:20:10		11/16/2022 16:51:55
Inventory Usage:		EMS, DRUG KIT EMS, ECG MONITOR EMS, JUMP BAG EMS, PULSE OXIMETER EMS, STRETCHER, SPECIFY EMS, VITALS MONITOR EMS, IV KIT	Unit Action Taken: Emergency medical services, Other Provide advanced life support (ALS) Transport person			
Unit Personnel:		Jordre, Tyler	DRIVER			
		Stagnitto, Michael	Officer in Charge (Or one person unit)			
Unit Narrative:		M731 dispatched on building explosion with injuries. M731 arrived on scene to side Charlie, found a priority patient, packaged, treated and transported patient to Suburban. Face to Face done with EMS703 prior to transport. M731 cleared the hospital and returned to scene to fill role of TRT asset. M731 returned to service at conclusion of TRT event.				





FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

TR700

11/16/2022 08:53:36	11/16/2022 12:01:45	11/16/2022 12:01:45			11/16/2022 16:43:46
Inventory Usage: TRT Equip, Specify		Unit Action Taken: Provide manpower Provide apparatus Provide equipment			
Unit Personnel: Neidhart, Christopher Kemp, Timothy		Officer in Charge (Or one person unit) DRIVER			
Unit Narrative: TR700 responded to a garden apartment for the report of an explosion w/ building collapse. AOS to staging. Neidhart assumed TRT-O. Assembled all TRT personnel at staging point. Divided into working squads. Established base of operations on Quince Orchard Blvd and staged personnel and equipment. Assisted w/ search operations. Placed in service by the Rescue Branch.					

PE734

11/16/2022 08:40:58	11/16/2022 08:41:27	11/16/2022 08:49:16			11/16/2022 16:19:42
Inventory Usage: HANDLINE, 2 - Put # ft in Quantity MASTER STREAM, REMOTE PUMP, FIXED SCBA SUPPLY LINE, 4 - Put # ft in Quantity		Unit Action Taken: Extinguishment by fire service personnel			
Unit Personnel: McKenna, Michael Mackenzie, Richard Rice, James Stoner, Andrew		Right DRIVER Officer in Charge (Or one person unit) Left			
Unit Narrative: 5TH ENGINE ON BOX ALARM DUE TO THE SIZE OF THE INCIDENT AND IMMEDIATE RESCUES, WE DID NOT ESTABLISH THE INITIAL RIC CO WE WERE THE FIRST UNIT TO ARRIVE ON SIDE C AND BEGAN IDENTIFYING VICTIMS AND SETTING UP HAND LINES. BYSTANDERS HAD MADE 2 RESCUES BEFORE WE ARRIVED, 1 OCCUPANT WAS WALKED OUT OF AN EXPOSURE UNIT WE EXTENDED A HANDLINE TO SIDE C TO EXTINGUISH FIRE AND PROTECT CREWS SEARCHING E732 ARRIVED AND I ASKED THEM TO BRING A 3" LINE TO ASSIST US, WHICH THEY OPERATED BESIDE US. I DIRECTED T725 TO A POSITION TO OPERATE FROM, WHICH THEY DID. WE CONTINUED TO FLOW WATER FOR HOURS AND OTHER DUTIES TO SUPPORT CREWS ON SIDE C NOTE- LATER IN THE INCIDENT A WORKER NEAR BY WITNESS THE EXPLOSTION AND WATCHED A MAN JUMP FROM THE 2ND FLOOR, THERE WAS A 2ND MAN THAT WOULD NOT JUMP HIS ARM WAS BROKEN SO A WORKER USED HIS LADDER AND CARRIED DOWN THE MAN.					

PE708



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

11/16/2022 08:40:58	11/16/2022 08:41:21	11/16/2022 08:44:08			11/16/2022 17:27:40
Inventory Usage:	FORCIBLE ENTRY TOOL, HAND HANDLINE, 1 1/2 - Put # ft in Quantity HANDLINE, 2 - Put # ft in Quantity LADDER, UNDER 20 FEET LADDER, 20-30 FEET SCBA SUPPLY LINE, 4 - Put # ft in Quantity		Unit Action Taken:	Fire control or extinguishment, other Extinguishment by fire service personnel Fires, rescues & hazardous conditions, Other Evacuate area	
Unit Personnel:	Sam, Tina Right Buckley, Derrick Officer in Charge (Or one person unit) Greer, Justin Left Jordan, David DRIVER				
Unit Narrative:	<p>PE708 dispatched for a building fire w/explosion and unknown address. Unknown address due to multiple calls and multiple different locations reported. Enroute acknowledged ECC's updated radio transmissions and had a column of smoke upon leaving the front ramp of Fire Company 8. The three different locations were close to each other but not close enough to call a single water supply. All three locations had a different water supply within 50-100'. PE708 advised PE731 of two possibilities for a hydrant but would confirm water supply once I could confirm building fire location, PE731 acknowledged. Approaching incident had to determine from QO Blvd. which driveway was the best access and the building involved. Picked the main driveway to the complex, once writer realized it was correct, we were already past the point of ability to reasonably lay out.</p> <p>PE708 aos with a 3 story garden apartment that had an obvious explosion due to debris including a door in the parking lot, had a partial collapse of the Charlie and delta quadrants, no obvious rescues visible side A, and fire from all three floors. PE708 crew while giving IOSR pulled 300' 2" to side A exterior and began flowing water. PE708 OIC while aos to confirm location saw the building and conditions but went back to the map book to confirm water supply we would be using. Advised PE731 taking the hydrant at 830 QO Blvd., they acknowledged as this was one of the two original possibilities. Upon exiting PE708, verbally acknowledged ECC advising reports of woman/baby on 3rd floor balcony along with did confirm the address of main fire building as 826 QO Blvd. After confirming the address and taking a moment to look at the building, realized it was two apartment buildings with collapse and not one. Collapse of 826 QO in the C and D quadrants along with A and B quadrants of 828 QO but BC703 arrived. With reports of person on balcony but no one on side A, quick face to face with PAT708 driver that I needed ladders to side C for possible rescue and I needed a side C report, [REDACTED] acknowledged. Maintenance man was out front was yelling at me that a kid or adult was trapped in the terrace level quadrant A apt of 826, slight language barrier but repeated and [REDACTED] said yes. PE708 OIC assessed the bowed out wall from the explosion but ventilated the window on side A at the B corner. No smoke came out and apartment was clear of smoke or fire. Could see the crib was vacant and yelled into the apt with no response. Due to the bowed wall and no confirmed reports of entrapment on the upper floors in the same area, wrote that section of 826 off due to further collapse potential (collapse already occurred of upper floor/attic). PE731 OIC approached asking what we needed. I advised main priority was assistance with hand jacking water supply line to their engine. PE731 immediately helped with establishing water supply which occurred quickly, the initial hand line never lost water. PE708 E4 made reasonable progress flowing exterior closest to the 828 stairwell to protect the search as best as possible.</p> <p>PE708 E3 advised to stretch a 300' 1.5" line to side A of 828 QO and that we were making entry. Line was stretched to the front door at which time PAT708 OIC advised he wanted the line to the top floor apartment. PE708 OIC noticed original conditions upon 828 stairwell door being opened as limited visibility with black smoke on the terrace level. PE708 OIC originally thinking there was 4 apartments per floor and possibility of terrace level apartment on fire. PE708 OIC advised PAT708 OIC I was not taking line to the top floor and that we would deploy to terrace level. Masked up and went in with PAT708 OIC to</p>				



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

terrace level where I realized there was only two apartments per floor and the fire door wall was intact with no obvious signs of fire or immediate show of concern to stay on the terrace level. Was also thinking due to collapse closest to side A the door would be difficult to force and entry other than at door way would not be likely. PE708 crew redeployed line to the top floor where called for line to be charged (was difficult getting radio time). As line was being redeployed, PE731 had arrived with another line and advised [redacted] was good with the lower units while we went to the top floor. Upon arrival to top floor encountered A/B apartment door glowing with better visibility at landing but no visibility in the C/D apartment. Advised to keep the A/B apt door shut as that was wrote off due to collapse and pulled attic scuttle in stairway. Due to seeing fire but some daylight in stairwell attic scuttle, line needed to be in C/D apt to control the horizontal extension. Other crews were already in the top floor performing searches and advised we had a hand line. PE708 crew got line into C/D apt kitchen, pulled stove out, shut gas off to stove, and personnel was placed on top of stove getting line flowing into the attic. PE708 crew just had got the line flowing for about 10 seconds when someone was advising within the building we were evacuating. PE708 OIC advised not knowing who was saying it from within the building, that we were in a great position, line just got into the attic, we were going to begin making progress, and we were not evacuating. Heard yelling to evacuate and told my crew to stay in place along with yelled back we were not evacuating. At that time BC705 was face to face identifying himself and ordered evacuation. Limited conversation occurred when PE708 followed evac orders. All PE708 crew confirmed they were ok and maintained line on top floor landing until it was confirmed all crews were out, made sure PE708 crew was last to exit due to having the handline. Upon exiting 828 QO, BC705 advised PE708 crew to get a line to the top floor of 830. PE708 crew deployed a cross lay off of PE729 which was closest to 830 to the top floor. Upon entry to top floor of 830, PE722 was already there with a charged hand line and advised attic was clear of fire. PE722 and T734 were sufficient resources on top floor of 830 and PE708 crew left line they deployed.

PE708 OIC tried to get back into 828 but BC705 denied request. At this time PE708 crew assisted exterior as needed along with switched out SCBA cylinders at a chance of redeployment. Once aerial master streams were shut down, BC705 reorganized PE708, PE731, and RS703 to complete secondary of 828. PE708 crew assisted with a hand line to the top floor but was not utilized. Gas meter room checked for on the terrace level but unable to find. Only found gas shut off for the dryers in the small laundry room located in the C quadrant of 828. Checked C quadrant apartment backing up to laundry room with no gas lines/meters located. All secondary searches of accessible areas completed and negative.

Crews assisted with miscellaneous tasks until being asked to assist with metering complex with PAT708 and HM728. As crews were about to assist, CMD advised he needed someone to flow a handline from PAT708 to knock down hot spots in coordination with Capt Shaffner for canine search potential. Did as instructed but fire was too deep seated to extinguish. Advised Capt Shaffner of the same and were ok with the task.

Crew performed other tasks as needed including assisting two residence of 830 with gathering belongings. PE708 crew packed hose with assistance of other companies before returning to service.

Company 8 and 31 crews performed exceptional work with the incident presented to them. Crews were on-scene for 9 hours with lots of physical labor and no complaints.

A702


11/16/2022 10:09:04	11/16/2022 10:17:44	11/16/2022 12:00:00			11/16/2022 17:28:02
Inventory Usage:	NO EQUIPMENT USED		Unit Action Taken:	Provide manpower	
Unit Personnel:	Ord, Joel Bryant, William		Officer in Charge (Or one person unit) DRIVER		
Unit Narrative:	PROVIDED MANPOWER FOR TRT RESPONSE.				



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

E729						
11/16/2022 08:40:58	11/16/2022 08:42:26	11/16/2022 08:50:13				11/16/2022 17:51:13
Inventory Usage: HANDLINE, 2 1/2 - Put # ft in Quantity		Unit Action Taken: Fire control or extinguishment, other Extinguishment by fire service personnel Provide manpower				
Unit Personnel: Lao, Nina		Right				
Hobbs, Brandon		Officer in Charge (Or one person unit)				
Root, Dan		DRIVER CERTIFIED				
Unit Narrative: 3RD DUE ON BUILDING FIRE W/EXPLOSION. TRIED TO GIVE WATER SUPPLY BUT TO MUCH RADIO TRAFFIC. PULLED 250 FT 2.5 ATTACK LINE AND EXTINGUISHED FIRE ON SIDE ALFA 826 QUINCE ORCHARD BLVD. ALSO PROTECTED BRAVO/CHARLIE EXPOSURE W/2.5" LINE. ASSET RELOCATED W/TRT TO BECOME TRT SAFETY OFFICER. STOOD-BY UNTIL DETERMINED TRT ASSETS NOT NEEDED TODAY. ASSISTED W/PICKING UP HOSE AND RETURNED TO SERVICE.						
EM700						
11/16/2022 15:48:48	11/16/2022 15:48:48	11/16/2022 15:52:16				11/16/2022 17:52:53
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Action taken, Other				
Unit Personnel: Ogren, Daniel		Officer in Charge (Or one person unit)				
Unit Narrative: Responded to Scene of Building Explosion/Collapse to assist FC and PIO with PIO Activities. In Service.						
TC700						
11/16/2022 08:50:28	11/16/2022 08:50:28	11/16/2022 09:24:49				11/16/2022 17:47:04
Inventory Usage:		Unit Action Taken:				
Unit Personnel: Baltrosky, Michael		Officer in Charge (Or one person unit)				
Unit Narrative:						
M729						
11/16/2022 09:23:21	11/16/2022 09:23:29	11/16/2022 09:25:12				11/16/2022 17:43:37
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Action taken, Other				
Unit Personnel: Decker, Joseph		DRIVER				
Unit Narrative: DRIVER ONLY, TRT RESOURCE						





FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878


PE731				
11/16/2022 08:40:58	11/16/2022 08:42:18	11/16/2022 08:46:43		11/16/2022 17:38:24
Inventory Usage:	HANDLINE, 2 - Put # ft in Quantity SCBA		Unit Action Taken:	Extinguishment by fire service personnel
Unit Personnel:	Ward, Thomas	Right		
	Hardesty, Chase	DRIVER		
	Pierce, Scott	Officer in Charge (Or one person unit)		
	Kough, Daniel	Left		
Unit Narrative:	<p>DISPATCHED AS 2ND DUE ENGINE COMPANY, ARRIVED AS 2ND DUE ENGINE COMPANY. WE WERE UNABLE TO INITIALLY CONFIRM A SOLID WATER SUPPLY PLAN DUE TO THE VARIOUS CONFLICTING INFORMATION ON WHICH STRUCTURE IT WAS. ONCE 8 CONFIRMED THE ADDRESS ENGINE 31'S CREW ASSISTED ENGINE 8'S DRIVER IN HANDJACKING A LINE TO ENGINE 31 WHICH WAS SITTING ON THE HYDRANT. A ONE AND A HALF IN CROSSLAY WAS ORIGINALLY DEPLOYED TO BEGIN KNOCKING DOWN VISIBLE FIRE. THAT HANDLINE WAS ABANDONED AND A TWO INCH LINE WAS DEPLOYED TO BUILDING 828 TO BACK UP AND ASSIST ENGINE AND TOWER 8'S CREWS. 31'S HANDLINE WAS PLACED IN THE ENTRY WAY/STAIRWELL TO KEEP THE FIRE IN THE A/B QUADRANTS IN CHECK WHILE THE THREE CREWS FORCED ALL THE DOOR IN 828 AND COMPLETED PRIMARY SEARCHES. ENGINE 31 ALONG WITH COMPANY 8 WERE PLACED UNDER THE COMMAND OF BATTALION CHIEF 5, CHIEF FITCH. AFTER COMPLETION OF INITIAL OPERATIONS IN 828, THE CREWS UNDERNEATH BATTALION 5 RE-DEPLOYED TO 830 TO COMPLETE SEARCHES AND CHECK FOR EXTENSION THROUGH. ENGINE 31'S CREW WAS THEN TASKED WITH BREACHING THE WALL IN BETWEEN 828 AND 830. A BLOCK FIREWALL WAS FOUND TO EXTEND UP THROUGH THE 3RD FLOOR SO NO BREACH WAS COMPLETED. ENGINE 31'S CREW WAS RE-DEPLOYED TO SIDE ALPHA OF 828 WITH A HANDLINE TO KEEP THE FIRE IN CHECK. ENGINE 31'S CREW WAS THEN RE-DEPLOYED TO THE BUCKET OF TOWER 3 TO GET UP TO THE ROOF LINE AND KNOCK ALL VISIBLE FIRE. AFTER THE VISIBLE FIRE WAS KNOCKED, ENGINE 31'S CREW WAS RE-DEPLOYED TO 828 TO COMPLETE SECONDARY SEARCHES AND LOOK FOR UTILITY SHUT-OFF, NONE WERE FOUND. ALL SECONDARY SEARCHES WERE NEGATIVE. A DOG WAS FOUND IN THE CHARLIE QUADRANT APARTMENT AND BROUGHT TO COMMAND. ENGINE 31'S CREW WAS RE-DEPLOYED TO SIDE ALPHA TO CONTINUE FLOWING WATER INTO 828. AFTER THE MAJORITY OF THE FIRE WAS KNOCKED, ENGINE 31'S OFFICER AND BACKSTEP CREW WERE RE-TASKED TO OPERATE WITH TRT. ENGINE 31'S DRIVER AND UNIT CONTINUED TO OPERATE AS THE WATER SUPPLY ENGINE.</p>			
BC701				
11/16/2022 13:07:19	11/16/2022 13:07:19	11/16/2022 13:40:08		11/16/2022 17:40:12
Inventory Usage:	NO EQUIPMENT USED		Unit Action Taken:	Action taken, Other
Unit Personnel:	Furst, Robert	Officer in Charge (Or one person unit)		
Unit Narrative:	<p>BC701 relieved BC703 at the scene of a building fire.</p> <p>As the fire branch leader, I followed up with HM728 to ensure that surrounding buildings were sampled for flammable gas. Also, I executed a demobilization plan to release the remaining 1st and 2nd alarm units. Finally, I was assigned to ensure that residents who wished to access building 830 and wanted materials out of 824 were able to do so.</p>			



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

UT703C						
11/16/2022 11:16:08	11/16/2022 11:20:46	11/16/2022 11:35:00				11/16/2022 16:59:36
Inventory Usage: NO EQUIPMENT USED			Unit Action Taken: Provide manpower			
Unit Personnel: Birbaum, Steve		Officer in Charge (Or one person unit)				
Unit Narrative: Responded with one TRT member. AOS to TRT staging. Supported TRT operations as assigned.						
AT703						
11/16/2022 08:42:23	11/16/2022 08:43:41	11/16/2022 13:14:52				11/16/2022 17:00:23
Inventory Usage: LADDER, ELEVATED PLATFORM MASTER STREAM, DECK GUN			Unit Action Taken: Provide manpower Provide apparatus Provide equipment			
Unit Personnel: Smith, Jr, Irvin		Officer in Charge (Or one person unit)				
Leonard, Matthew		DRIVER CERTIFIED				
Dixon, Kyle		Left				
Unit Narrative: ASSISTED WITH ELEVATED MASTER STREAMS TO SUPRESS FIRE AND HOT SPOTS ON A BUILDING EXPLOSIAN.						
A708B						
11/16/2022 08:47:27	11/16/2022 08:47:37	11/16/2022 08:55:14				11/16/2022 17:09:25
Inventory Usage: EMS, JUMP BAG EMS, PULSE OXIMETER EMS, VITALS MONITOR			Unit Action Taken: Provide first aid & check for injuries Provide basic life support (BLS)			
Unit Personnel: Denard, Darlington		Officer in Charge (Or one person unit)				
Maccrone, Tyler		DRIVER				
Unit Narrative: REHAB						
DC700						
11/16/2022 08:49:22	11/16/2022 08:49:22	11/16/2022 08:55:00				11/16/2022 17:09:37
Inventory Usage: CAMERA, SPECIFY			Unit Action Taken: Incident command Notify other agencies. Refer to proper authority			
Unit Personnel: Nelson, Michael		Officer in Charge (Or one person unit)				





FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

Unit Narrative: DC700 received a phone call from the ECC Supervisor that there was a loud explosion and large column of smoke in the vicinity of ECC. ECC was attempting to locate the address and they were receiving calls.

DC700 responded on Box 08-23 for 826 Quince Orchard Blvd for a building fire w/ reported explosion.

BC703 arrived on scene, established command, requested a 2nd alarm and multi-patient dispatch. Command reported a garden apartment well involved with fire and collapse.

DC700 arrived on scene w/ the Scheduling Officer. Had the scheduler report to the CP to assist command. DC700 started a 360 and photographing for command. Had PE734's officer establish a collapse zone on side Charlie. On side Bravo, instructed MCPD & GPD to evacuate 824 Quince Orchard Blvd. Reported to Command Post and assisted BC703 & HMB700 with Command. Command had exterior operations in place and units were entering 830 to cut the fire spread off. EMS BC700B was in charge of the EMS Branch.

C700 was on scene and advised me to handle the fire incident with Command and he would take care of the other stuff. OEMHS, PD, Media, TRT...

Rapid primary searches were conducted of 824, 828, 830 & 832. Reported negative. EMS Branch advised 2 traumas to Suburban and initially 6 others going to HCH-Germantown via MAB726. The would later be revised to hospital destination to keep families together.

Fire was brought under control and shift in operational function to building stabilization, occupant accountability and investigation.

Worked ensure we had a collection point for displaced occupants, utility control and rehab for FD personnel.

Safety 700 established collapse zones around the structure.

OC700 arrived and assumed the Command and BC703 became the Fire Suppression Branch.

DC700 transition to assisting command with the support functions.

Requested CMF Staff to evaluate T725, which had sunk in the mud and its recovery.

Requested BC701 to scene to relieve BC703.

Developed plan for units to maintain safety & security of the site until the morning operational period.

Placed in service by command and advised OE700 of resumption of County control.

DC700 ready for service.

WUUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

PE732					
11/16/2022 08:40:58	11/16/2022 08:41:14	11/16/2022 08:49:05			11/16/2022 17:09:36
Inventory Usage:	SUPPLY LINE, 3 - Put # ft in Quantity SUPPLY LINE, 4 - Put # ft in Quantity		Unit Action Taken: Extinguishment by fire service personnel		
Unit Personnel:	Nelson, Brenton DRIVER Sito Jr., Robert Left Sunier, Alexander Right Artingstall, Thomas Officer in Charge (Or one person unit)				
Unit Narrative:	Dispatched as the 4th due engine to the listed address. PE729 as 3rd due advised they would be utilizing the hydrant at 800 Quince Orchard Blvd. Upon arrival, it was evident this hydrant was unable to be utilized by PE729 due to being blocked out by 1st due units. I advised my operator to drive to the parking lot on the Charlie side of the incident where PE734 had their own hydrant. PE732 co-located with PE734 and assumed 4th due engine responsibilities. After a face to face with the officer of PE734, the crew from PE732 advanced a 3" line to the Charlie side of 826/828 and assisted PE734 with extinguishing fire from a defensive position. A face to face was also done with the officer of PE729 to communicate the change in water supply. The occupant of 824 T2 was found to be still in his apartment. Occupant was assisted out the charlie side of his unit and directed to an area of safety with no need for EMS. PE732 operated for quite some time, extinguishing fire and hitting spots until released by command.				
T725					
11/16/2022 08:47:27	11/16/2022 08:48:46	11/16/2022 08:55:15			11/16/2022 17:16:52
Inventory Usage:	FORCIBLE ENTRY TOOL, HAND		Unit Action Taken: Extinguishment by fire service personnel Forcible entry		
Unit Personnel:	McCarter, Andrew Officer in Charge (Or one person unit) Krebs, Richard DRIVER Dipietro, Dominic TILLER				
Unit Narrative:	Arrived as the truck on the 2nd alarm to get position on side C of the structure. Crew was tasked with searching the neighboring apartment units while the driver set up for master stream operations. All searches were negative and no extension was found in the 824 building. Master stream operations continued until fire was knocked down. Crews then switched to a TRT roll and went to TRT staging.				
ALS725					
11/16/2022 09:56:58	11/16/2022 09:57:08	11/16/2022 10:08:38			11/16/2022 17:20:39
Inventory Usage:	NO EQUIPMENT USED		Unit Action Taken: Search & rescue, Other		
Unit Personnel:	Abramovitch, Steven Officer in Charge (Or one person unit) Denaburg, David DRIVER				
Unit Narrative:	Dispatched to location for reported building fire with explosion. ALS725 sent as support unit for TRT compliment. Cleared in evening during closing of operations.				



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

MAU716

11/16/2022 08:51:37	11/16/2022 08:56:26	11/16/2022 09:15:00			11/16/2022 17:22:45
Inventory Usage:	NO EQUIPMENT USED	Unit Action Taken:	Assistance, Other		
Unit Personnel:	Newman, Nicholas	Officer in Charge (Or one person unit)			
	Donaldson, Brandon	DRIVER			
Unit Narrative:	ASSISTED UNITS ON SCENE WITH FILLING CYLINDERS AFTER BUILDING EXPLOSION				

WUSA



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

PAT708			
11/16/2022 08:40:58	11/16/2022 08:41:12	11/16/2022 08:43:00	11/16/2022 17:23:11
Inventory Usage:	FORCIBLE ENTRY TOOL, HAND LADDER, ELEVATED PLATFORM LADDER, 20-30 FEET LADDER, OVER 30 FEET MASTER STREAM, ELEVATED OTHER EQUIP, FIRE, SPECIFY SCBA MX6-Meter	Unit Action Taken:	Search Forcible entry Operate apparatus or vehicle Provide manpower Provide apparatus Provide equipment
Unit Personnel:	Escolero, Enrique Officer in Charge (Or one person unit) Henry, Tommy DRIVER Hollenbach, Athena Left Jessa, Christopher Right		
Unit Narrative:	<p>PAT708 was dispatched as the first due Truck company to calls in the area of Quince Orchard BLVD. First due companies arrived onscene to a 3 story apartment building with collapse and fire showing on the alpha side in the Echo quadrant, and extending into exposures. Dispatch notified company 8 of a potential rescue (a woman and baby) from a balcony. Message was acknowledged. An individual on side A stated that they attempted to clear the Delta exposure, but was unable to due to conditions. PAT708 split crews, and were simultaneously throwing ladders to the charlie side, setting up for aerial master stream, and searching the delta exposure. Crews from PAT708 working on C side threw ladders (16ft, 20ft, 28ft, 35ft) to locate the civilian in distress, with no one found; they continued to ves the third floor to ensure no occupant trapped. Personnel on side A entered 828 (Delta exposure), and forced entry to the second floor apartment adjacent to the fire building, noticing a collapse into the apartment (with only a primary done in the main living area). The third floor door adjacent to the fire building was left intact due to obvious flames, awaiting for a deployed handline. The second apartment (across) on the third floor was forced, and quickly searched with minimal visibility in the apartment.</p> <p>It was noticed that pe708 redeployed their handline to the Delta exposure, and crews on the A side continued to pop doors other apartment on the second floor. An update was given to the engine company that they needed to get a line on the fire apartment, and they requested that we pop the doors in the basement. Vibarliert noticed, decided to exit PAT708 side A crew to the outside to replace cylinders and go back to work. Advised command that we could help, Command advised that we could go into the top floor apartment of the delta Exposure, however we were immediately removed and redeployed to the D1 Exposure with PE722. Checked the D1 exposure, found no conditions in the attic area, and a primary was completed on the bottom floor. Advised PE722 that we would exit and assist on the A side (since they had t734) and all tasks were complete. They were ok on the message, command re deployed us to assist with A side extinguishment. The tower driver continued to assist with extinguishment from the master stream after people were evacuated from the D exposure.</p> <p>Personnel were able to regroup, and rehab. Once ready PAT708 was tasked to assist HM728 with clearance of the apartment buildings in the 700block of Quince Orchard Blvd with an MX6. Task completed, and no readings found.</p> <p>Personnel operated with full PPE/ SCBA.</p>		



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

FM720					
11/16/2022 09:07:06	11/16/2022 09:07:06	11/16/2022 09:35:35			11/16/2022 19:26:44
Inventory Usage: BOMB SUIT FEI Equip, Specify		Unit Action Taken: Information, investigation & enforcement, Other Investigate			
Unit Personnel: Gettig, Andrew		Officer in Charge (Or one person unit)			
Unit Narrative: Called back to assist on the investigations of the building explosion. Interviewed witnesses and victims. During the investigation, the vehicle belonging to a missing subject thought to be suicidal was discovered in the parking lot in front of the building. After obtaining a search warrant, FM 720 along with FM 721, both certified hazardous device technicians (bomb techs), donned a higher level of protective gear and using a vehicle lock out kit, gained access into the vehicle. No hazards were discovered but items aiding in the origin and cause of the explosion/fire were discovered and handed over to the lead investigators and MCP Major Crimes division. No other services rendered.					
FM740					
11/16/2022 08:46:28	11/16/2022 08:46:28	11/16/2022 08:51:09			11/16/2022 19:47:24
Inventory Usage: FEI Equip, Specify		Unit Action Taken: Information, investigation & enforcement, Other Investigate			
Unit Personnel: Wirth, Erin		Officer in Charge (Or one person unit)			
Unit Narrative: Responded for the building explosion. Arrived on scene and began occupant accountability of buildings 824, 826, 828 and 830. The origin and cause examination was performed over the next few days. See eJustice report for further information.					
FM721					
11/16/2022 09:17:51	11/16/2022 09:17:51	11/16/2022 09:25:03			11/16/2022 20:27:18
Inventory Usage: CAMERA, SPECIFY FEI Equip, Specify		Unit Action Taken: Investigate			
Unit Personnel: Olin, William		Officer in Charge (Or one person unit)			
Unit Narrative: Assisted on the building explosion investigation.					





FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

FM719						
11/16/2022 12:32:35	11/16/2022 12:32:42	11/16/2022 12:42:00				11/16/2022 20:02:04
Inventory Usage:	CAMERA, SPECIFY EVIDENCE CONTAINERS FEI Equip, Specify		Unit Action Taken: Investigate			
Unit Personnel:	Wolowicz, Philip Officer in Charge (Or one person unit)					
Unit Narrative:	Reported to FM710, on scene from Wednesday till Friday. Collected evidence and logged it into Traq. Marked vehicle locations, marked blast debris. Assisted in planning for the placement of temp security fencing to preserve evidence. Documented scene with digital photography for evidentiary value and downloaded images into Traq.					
FM711						
11/16/2022 09:23:41	11/16/2022 09:23:41	11/16/2022 17:24:09				11/16/2022 20:05:34
Inventory Usage:	ACCELERANT CANINE		Unit Action Taken: Investigate			
Unit Personnel:	Moe, Christopher Officer in Charge (Or one person unit)					
Unit Narrative:	Responded to assist on the scene of a building explosion with investigative responsibilities and ADC					
FM730						
11/16/2022 08:46:00	11/16/2022 08:46:00	11/16/2022 08:51:04				11/16/2022 20:06:28
Inventory Usage:	CAMERA, SPECIFY EVIDENCE CONTAINERS FEI Equip, Specify		Unit Action Taken: Investigate			
Unit Personnel:	Bise, James Officer in Charge (Or one person unit)					
Unit Narrative:	Responded for the building explosion. Arrived on scene and began scene assessment. Origin and cause examination performed over the course of several days, that included recovery of victim. See eJustice report for further report information.					
FM712						
11/16/2022 09:55:56	11/16/2022 09:55:56	11/16/2022 10:10:54				11/16/2022 20:59:18
Inventory Usage:	CAMERA, SPECIFY FLOODLIGHT TOOL, HAND, LRG (SHOVEL, AXE, etc) TOOL, HAND, SM (HAMMER, WRENCH, etc) FLASHLIGHT HELMET FEI Equip, Specify		Unit Action Taken: Provide manpower Provide equipment Investigate			
Unit Personnel:	Veith, III, Anthony Officer in Charge (Or one person unit)					
Unit Narrative:	Assisted units on scene with witness interviews, photos, area canvass, and investigations.					



FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

FM722					
11/16/2022 08:48:22	11/16/2022 08:48:22	11/16/2022 08:58:00			11/17/2022 00:48:21
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Search & rescue, Other Provide first aid & check for injuries Hazardous condition, Other Provide manpower Investigate			
Unit Personnel: Hade, Jason		Officer in Charge (Or one person unit)			
Unit Narrative: FM722 (HADE, 9207) arrived on the scene shortly after dispatch. Immediately met with crew from M731 and assisted moving patient to cot and then to the unit. While moving the patient, FM722 attempted to interview the subject regarding his identity, location in building, and sequence of events. FM722 then identified more patients and assisted in moving them to the EMS staging area in the Clubhouse. [REDACTED] conducted initial interviews of residents to obtain identification and contact information. FM722 then took photographs of the scene and later added them to TRAQ. FM722 proceeded to the PSCC to check call history at the incident location. FM722 accompanied Captain Wirth to interview a relative of a missing resident. Upon completion of the interview, FM722 went off-duty.					
HMB700					
11/16/2022 08:45:12	11/16/2022 08:45:12	11/16/2022 17:28:58			11/17/2022 06:10:18
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Action taken, Other Information, investigation & enforcement, Other Incident command			
Unit Personnel: Browning, Ivan		Officer in Charge (Or one person unit)			
Unit Narrative: SELF DISPATCH ON BLDG FIRE W/EXPLOSION AND ENTRAPMENT. AOS AND REPORTED TO ICP. ASSISTED AS 2ND CCO WITH IC (BC MANN). ONCE INCIDENT STABLIZED, ASSIGNED AS PLANNING SECTION CHIEF FOR LONG-TERM INCIDENT NEEDS. WORKED PLANNING SECTION TO ESTABLISH CURRENT AND FUTURE NEEDS. CAPT RANDALL AND CAPT KURLAND ASSIGNED WITH ME. AT 1700HRS, WORKED WITH AC MCDONALD FOR OVERNIGHT IC COVERAGE AND COORDINATION.					





FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

CP718

11/16/2022 09:05:13 11/16/2022 10:09:40 11/16/2022 10:09:40 11/17/2022 06:12:21

Inventory Usage: Unit Action Taken:

Unit Personnel:

Unit Narrative:

SP700

11/16/2022 09:10:42 11/16/2022 09:10:42 11/16/2022 17:29:18 11/17/2022 06:12:07

Inventory Usage: NO EQUIPMENT USED Unit Action Taken: Action taken, Other

Unit Personnel: McDonald, Tracy Officer in Charge (Or one person unit)

Unit Narrative: Dispatched to fire explosion. oversaw the special operations for TRT and FEI during the call. Maintained coverage in the command bus overnight and through the incident.

OC700

11/16/2022 10:00:00 11/16/2022 10:00:00 11/16/2022 10:00:00 11/16/2022 18:00:00

Inventory Usage: NO EQUIPMENT USED Unit Action Taken: Incident command


Unit Personnel: Bailey, Charles DRIVER

Unit Narrative: OC700 arrived well into the incident. Upon my arrival all patients has been transported and the overwhelming majority of the fire had been extinguished. Detailed operational summaries can be found in the respective unit reports.

OC700 assumed command in order to coordinate the "whole of County" response. Established five objectives:

- 1-Ensure awareness of situation: Use observers | Assign scribes | Use MSTeams | Maintain contact list (ICS205T)
- 2-Limit damages: Limit spread | Avoid additional damage to structures | Avoid additional damage to personal belongings
- 3-Reduce 2nd order impact to community: Reconsider road closures | Consider impact to local business | Reduce incident footprint
- 4-Secure the scene: Control entry | Only restrict what is necessary
- 5-Support community recovery: Ensure OEMHS is properly resourced | Provide logistical support to OEMHS

Command: OC700
 SpecOps Branch: SpecOps AC | Investigations Group & Tech Rescue Group
 Logistics Section: OEMHS-Laboy, FRS Baltrotsky
 Suppression Branch: BC703
 Security Branch: GPD Lt.
 Community Welfare Branch OEMHS-Cristomos





FireApp Incident Report

22-00143830 11/16/2022 08:40:12 826 QUINCE ORCHARD BLVD GAITHERSBURG MD 20878

C700

11/16/2022 08:41:00	11/16/2022 08:42:00	11/16/2022 08:52:00			11/16/2022 18:30:00
Inventory Usage: NO EQUIPMENT USED		Unit Action Taken: Assistance, Other			
Unit Personnel: Goldstein, Scott		Officer in Charge (Or one person unit)			
Unit Narrative: <ul style="list-style-type: none">- responded from home- aos and did lap and then assisted at CP- worked with MCPD and GCPD and Support services staff on- pool house opening for shelter and CCP- mcps liaison for brown station elementary- MCPD drone- OEMHS support- unit cleared					

WUSA