Loudoun County Work Order Adult Detention Center

Work Order Details:

WORK ORDER NO

22 356159

STATE:

Closed

STATUS:

Closed

New Note

| Note | User | Create Date | Last Updated | Edit | Delete |
|--|------------|--------------------------------------|-------------------------|-------------|---------------|
| Inmates state the water in the cells and shower in Medical are way to HOT. They are unable to stand under the water while in the shower. | Guest User | Saturday, 1/22/2022 8:50:02 AM | 1/22/2022 8:50:02 AM | <u>Edit</u> | <u>Delete</u> |

Closing Notes

| Note | User | Create Date | Last Updated | Edit | Delete |
|---|------|-------------------------------------|--------------------------|-------------|---------------|
| Made adjustments to the mixing valve and will continue to monitor | | Monday, 1/24/2022 12:52:07 PM | 1/24/2022 12:52:07 PM | <u>Edit</u> | <u>Delete</u> |

Work Order Details:

WORK ORDER NO

22 356419

STATE:

Closed

STATUS:

Closed

New Note

| Note | User | Create Date | Last Updated | Edit | Delete |
|--|------|-------------------------------------|-------------------------|-------------|---------------|
| Made adjustments to the 804 Mixing Valve. Water was to Hot | | Tuesday, 1/25/2022 3:05:18 PM | 1/25/2022 3:05:18 PM | <u>Edit</u> | <u>Delete</u> |

Closing Notes

| Note | User | Create Date | Last Updated | Edit | Delete |
|---|------|-------------------------------------|-------------------------|------|---------------|
| Rebuild the valve and made the proper water adjustments | | Tuesday, 1/25/2022 3:09:12 PM | 1/25/2022 3:09:12 PM | Edit | <u>Delete</u> |

Loudoun County Work Order Adult Detention Center

Work Order Details:

WORK ORDER NO 22 356641

STATE:
Closed
STATUS:
Closed
New Note

| Now Hote | | | |
|---|------|------------------------------------|-------------------------|
| Note | User | Create Date | Last Updated |
| Medical Inmate Shower - Inmates have complained that the hot water in the shower is too hot and can cause burns. The staff bathroom in the hallway, which most likely runs off the same water, has hot water that is too hot also. There was a previous sprocket from 1-24-22 about this same issue and it said that maintenance is monitoring the issue. It does not | | Friday, 1/28/2022 5:23:43 AM | 1/28/2022 5:23:43 AM |

Closing Notes

| Note | User | Create Date | Last Updated | Edit | Delete |
|--|------|---------------------------------------|-------------------------|-------------|---------------|
| The Mixing valve has been pulled apart and checked for any blockage from adjustment. the valve has been put back together and adjustments have been made | | Wednesday, 2/2/2022 10:26:54 AM | 2/2/2022 10:26:54 AM | <u>Edit</u> | <u>Delete</u> |

Edit Delete

Edit Delete

Work Order Details:

appear that the previous adjustment was sufficient.

WORK ORDER NO

22 357329

STATE:

Closed

STATUS:

Closed

New Note

| Note | User | Create Date | Last Updated | Edit | Delete |
|---|------|-------------------------------------|------------------------|-------------|---------------|
| check mixing valve for support building | | Saturday, 2/5/2022 5:37:15 PM | 2/5/2022 5:37:15 PM | <u>Edit</u> | <u>Delete</u> |

Closing Notes

| Note | User | Create Date | Last Updated | Edit | Delete |
|---|------|------------------------------------|------------------------|------|---------------|
| Feb 8 2022 7:51AM replaced mixing valve in support building for hot waterPer Tech | | Tuesday, 2/8/2022 9:03:34 AM | 2/8/2022 9:03:34 AM | Edit | <u>Delete</u> |